



PSNI Transport Services

Vehicle Service History - GFZ5135 VOLKSWAGEN TRANSPORT

*This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.*

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
S109882	0	REPAIRS		PARTS ONLY ORDER DRIVER DOOR MIRROR MT OFFICER WILL FIT TO VEHICLE BACK @ STATION
SA08134	145	MAIN JOB HEADER	31-Oct-2011	ALLOCATION (COACH BUILDER)
S65980	6,415	SAFETY CHECK	05-Oct-2012	SAFETY INSPECTION
S69278	10,593	MAJOR SERVICE	13-Feb-2013	MAJOR SERVICE/BFF/WIPERS/FILTERS/TYRES CHECK ALL TYRES
S69730	10,593	WARRANTY REPAIR	18-Feb-2013	FLASHING AMBER LIGHTS DEF.(WARRANTY REPAIR)
S76689	19,473	TYRES	27-Nov-2013	FIT BOTH FRONT TYRES WITH WINTER TYRES

*This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.*

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
UX01538	0	MAJOR SERVICE	17-Feb-2014	CARRY OUT MAJOR SERVICE MT11/1B 154055
S84443	31,201	REPAIRS	21-Nov-2014	BLANCE FRONT WHEELS REPLACE REAR TYRES REPLACE NUMBER PLATE DRIVE LIGHTS AND WIPERS
UX01861	33,474	MAJOR SERVICE	18-Feb-2015	MAJOR SERVICE CHANGE OIL & FILTER REPLACE BULBS CHANGE BRAKE FLUID REPLACE FRONT WIPER BLADES
ST06257	0	TYRES	28-Jan-2016	PLEASE REPAIR PUNCTURE TO LOOSE WHEEL WHEEL LEFT AT BACK DOOR
S93277	42,997	MAJOR SERVICE	16-Feb-2016	MAJOR SERVICE
S96951	48,131	REPAIRS	08-Jul-2016	REPLACE ALL BATTERIES
S98402	50,942	REPAIRS	05-Oct-2016	REPLACE REAR TYRE & CHECK FRONT BOTTOM HINGE ON DRIVERS DOOR BROKEN FRONT NUMBER PLATE DEFECTIVE
S00706	54,653	MAJOR SERVICE	16-Feb-2017	MAJOR SERVICE CHECK & REPLACE TYRES IF REQUIRED
S101383	56,829	REPAIRS	20-Apr-2017	THE COMBINED SMOKE/C02 DETECTOR HAS BEED REPORTED FAULTY IT IS FITTED TO THE INTERIOR
S103882	60,547	REPAIRS	13-Sep-2017	XXXX PARTS ONLY XXXX REPLACE VEHICLE BATTERY MT OFFICER TO FIT
S105847	64,727	MAJOR SERVICE	20-Feb-2018	MAJOR SERVICE BRAKE FLUSH CHECK & REPLACE TYRES AS REQUIRED BOOKED - 20/02/18

*This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.*

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
S108041	67,450	REPAIRS	02-Jul-2018	FLAT TYRE O/S/F
S109086	69,640	REPAIRS	12-Sep-2018	CHECK FOR BRAKE SHUDDER.
S112250	74,690	TYRES	12-Apr-2019	BOTH FRONT TYRES ARE WORN BADLY @ OUTSIDE EDGE & HAVE CUTS - STEERING BADLY CHECK STEERING FOR WEAR
S114822	78,556	MAJOR SERVICE	29-Aug-2019	MAJOR SERVICE BRAKE FLUSH CHECK & REPLACE TYRES/WMPERS BLADES IF REQUIRED
S117974	85,455	TYRES	19-Feb-2020	REPLACE TYRES AS REQUIRED DRIVER WAITING ON VEHICLE BOOKED FOR 19/2/20
S120138	93,714	MAJOR SERVICE	22-Jul-2020	MAJOR SERVICE BFF CHECK 240V PLUG ON SIDE OF VEHICLE FIT DAY TIME LIGHT BULBS
M05495	96,754	REPAIRS	29-Sep-2020	MOBILE WOPRKSHOP NO POWER TO CCTV UNIT
S121092	0	REPAIRS	01-Oct-2020	NO POWER TO CCTV UNIT ** ROADS POLICING HAVE NEW HARD DRIVE ORDERED FOR THIS VEHICLE **
M06315	102,211	REPAIRS	24-Mar-2021	MOBILE WORKSHOP VEHICLE BATTERY DUFF, PLEASE REPLACE - BATTERY EXIDE 74AH EB740 680