



PSNI Transport Services

Vehicle Service History - IGZ2796 SKODA OCTAVIA EST 2.

*This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.*

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
E16427	11,650	TYRES	09-May-2019	X1 TYRE
AXC00810	14,083	COLLISION	22-May-2019	PLEASE REPAIR ACCIDENT DAMAGE TO FRONT BUMPER ACC REF NO 92388/19/001C EST REF NO RDW03854
A62493	14,119	MAJOR SERVICE	10-Jun-2019	MAJOR SERVICE FUEL FILTER B/F/F
E16551	20,404	TYRES	23-Jul-2019	REPLACE TYRE
E16575	23,476	TYRES	07-Aug-2019	REPLACE FRONT TYRES NEW TYRES TO BE FITTED TO REAR OF VEHICLE
E16599	25,606	TYRES	21-Aug-2019	CHECK TYRES

***This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.***

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
E16667	30,461	MAJOR SERVICE	25-Sep-2019	MAJOR SERVICE B/F/F FUEL FILTER
E16727	38,501	TYRES	04-Nov-2019	REPLACE ONE TYRE O/S/R
E16730	39,247	TYRES	05-Nov-2019	REPLACE PUNCTURED TYRE PLACE NEW TYRE TO REAR OF VEHICLE
E16746	40,177	TYRES	11-Nov-2019	CHECK PUNCTURE N/S/F WHEEL NEW TYRES TO BE PLACED ON REAR OF VEHICLE
E16751	45,714	MAJOR SERVICE	03-Dec-2019	ORDER AND FIT FIVE 205/55/16 WINTER TYRES MAJOR SERVICE PUT OUT SERVICE LIGHT
SC00470	0	REPAIRS	05-Dec-2019	FRONT NO PLATE & BLUE LIGHTS AT REAR OF PLATE BENT
EX02541	55,742	REPAIRS	12-Feb-2020	PLEASE TRAVEL TO WORKSHOP PSNI STATION ENNISKILLEN REPLACE FRONT WINDSCREEN TRP FLSU 7D0000 40011
EC00038	56,968	COLLISION	02-Mar-2020	REPLACE / REPAIR LOWER ENGINE COVERS AND UNDER BODY PANELS HQ REF 92388/20/001
AX10100	7,237	REPAIRS	18-Mar-2020	PLEASE TRAVEL TO COOKSTOWN PSNI STATION AND REPLACE WINDSCREEN TRP FLSU 7D0000 40011
E16970	61,000	MAJOR SERVICE	24-Mar-2020	MAJOR SERVICE FUEL FILTER B/F/F
E17008	64,769	REPAIRS	15-Apr-2020	WIRE HANGING DOWN BELOW ENGINE

***This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.***

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
E17084	69,863	REPAIRS	26-May-2020	CHECK FOR OIL SENSOR LIGHT INTERMITTENT FAULT
E17135	75,574	MAJOR SERVICE	22-Jun-2020	MAJOR SERVICE BFF FUEL FILTER
E17179	79,331	TYRES	15-Jul-2020	REPLACE O/S/F TYRE
E17199	81,513	REPAIRS	27-Jul-2020	ROAD TEST AND DIAGNOSTIC
E17213	84,177	TYRES	11-Aug-2020	REPLACE TYRE
EC00043	84,814	COLLISION	19-Aug-2020	CHECK AND REPAIR ACCIDENT DAMAGE HQ REF 92388/20/003
E17282	88,940	TYRES	23-Sep-2020	PUNCTURE O/S/R
E17291	90,000	MAJOR SERVICE	29-Sep-2020	MAJOR SERVICE FUEL FILTER B/F/F
E17319	20,235	TYRES	20-Oct-2020	REPLACE X1 TYRE
AT07898	98,654	TYRES	01-Dec-2020	REPLACE ONE TYRE
E17395	100,146	REPAIRS	16-Dec-2020	CHECK REPORTED PROBLEM FRONT NEAR SIDE WHEEL

***This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.***

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
A67387	102,331	REPAIRS	05-Jan-2021	DEF CLUTCH
E17432	103,985	REPAIRS	19-Jan-2021	EML LIGHT ON
A67517	103,668	MAJOR SERVICE	21-Jan-2021	MAJOR SERVICE FUEL FILTER B/F/F EML LIGHT ON
A67533	103,668	REPAIRS	25-Jan-2021	REPLACE STEERING WHEEL AIRBAG EML LIGHT ON DEF A/C
E17544	115,589	REPAIRS	20-Apr-2021	REPLACE TYRES CHECK BODY UNDER COVER
E17553	116,655	REPAIRS	28-Apr-2021	CHECK OPERATION OF CLUTCH
E17564	117,800	MAJOR SERVICE	05-May-2021	MAJOR SERVICE FUEL FILTER B/F/F CHECK REPORTED RATTLE FROM FRONT SUSPENSION
E17601	119,864	REPAIRS	24-May-2021	LOW BEAM NOT WORKING
E17612	120,820	REPAIRS	01-Jun-2021	DEF O/S LOW BEAM
A68689	121,380	REPAIRS	08-Jun-2021	CHECK OPERATION OF CLUTCH
EX02587	123,412	REPAIRS	30-Jun-2021	PLEASE INSPECT & REPAIR CLUTCH. CLUTCH WAS RENEWED IN JANUARY THERE HAVE BEEN SEVERAL INSTANCES OF CLUTCH PEDAL STAYING DOWN ON THE FLOOR.

***This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.***

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
E17681	124,679	TYRES	19-Jul-2021	REPLACE BOTH FRONT TYRES
E17695	125,784	REPAIRS	27-Jul-2021	CHECK OIL SENSOR FAULT
E17773	132,000	MAJOR SERVICE	13-Sep-2021	MAJOR SERVICE FUEL FILTER B/F/F CHECK TYRES REPORTED SLOW PUNCTURE
E17832	137,604	TYRES	22-Oct-2021	REPLACE X1 TYRE
ET00234	138,591	TYRES	01-Nov-2021	TWO PUNCTURE
E17841	140,604	REPAIRS	16-Nov-2021	DRIVERS SEAT BACK SPONGE AND COVER CHECK REPORTED RATTLE FROM FRONT SUSPENSION
A70039	140,620	REPAIRS	26-Nov-2021	CHECK SEAT FOR CRACK REPLACE SEAT BACK SPONGE AND COVER CHECK REPORTED FRONT SUSPENSION RATTLE BATTERY
E17952	147,054	MAJOR SERVICE	24-Jan-2022	MAJOR SERVICE BRAKE FLUID FLUSH X2 FRONT TYRES SERVICE LIGHT ON
E17966	149,020	REPAIRS	07-Feb-2022	CHECK OIL LIGHT ON
E18027	152,759	TYRES	15-Mar-2022	REPLACE TYRE
E18069	156,271	REPAIRS	11-Apr-2022	CHECK FOR WIRE HANGING CHARGE BULBS FITTED PREVIOUSLY

*This is the history of the maintenance and repairs carried out on the above vehicle whilst owned by the PSNI
Please note this is for information purposes only. The vehicle is 'sold as seen'.*

<u>Job Ref</u>	<u>Odometer</u>	<u>Job Title</u>	<u>Booked in</u>	<u>All Job Notes</u>
ET00260	0	TYRES	05-May-2022	FIT TYRES LOOSE WHEELS